PRESCALE FOR HIGH TEMPERATURE

Pressure Measurement Film

Prescale for High Temperature

GUIDE

Just cut Prescale and insert to the place you want to inspect.
Prescale for High Temperature visualizes pressure of heat pressing with its color density.



Cut Prescale into any size or shape of your choice.

Apply pressure and a color appears to where pressure is applied.

Visually confirm using Prescale Color Chart. Also, quantify with FUJIFILM Prescale Mobile.

CHARACTERISTICS

Measure pressure under heat conditions (35℃～150℃／150℃～220℃).



LINE-UP

Prescale for High Temperature 100 (Recommended temperature: 35°C～150℃)

Types	Measurable pressure range [MPa] (0.006 0.05 0.2 0.5 0.6 2.5 10 50 130 300)	Product size width(mm)×length(m)
Ultra Super Low Pressure (LLLW)		270×5
Super Low Pressure (LLW)		270×6
Low Pressure (LW)		270×10

Prescale for High Temperature 200 (Recommended temperature: 150°C～220℃)

Types	Measurable pressure range [MPa] (0.006 0.05 0.2 0.5 0.6 2.5 10 50 130 300)	Product size width(mm)×length(m)
Ultra Super Low Pressure (LLLW)		270×5
Super Low Pressure (LLW)		270×6
Low Pressure (LW)		270×10